

Knowles/Parsonage Brook outfall in the Buckeye Brook Watershed  
Photos taken 7/5/14 & submitted by Elaine Papa, Buckeye Brook Coalition



4437 downstream at concrete outfall - George's Pizza (red building) in background to right of monitoring site at end of parking lot



4441 bottles for dissolved oxygen testing (waiting for flocculant to settle before final "fix")



4442 Rt. 117A Warwick Avenue - monitoring site - behind green bin and right of street light. (Morris Farm is far left.)





4443 intersection Rt. 117A and 117 - parking lot length to monitoring site



4444 parking lot with eroded bank (approximately 12 spots in length to the right of green bin)





4447 parking lot edge overlooking brook growth



4449 monitoring site - side view of concrete outfall - brook runs behind Morris Farm under Rt. 117A to monitoring site